



September 29, 2026

Mr. Joseph Adamczak, P.E.
Greenman-Pederson, Inc.
80 Wolf Road, Suite 300
Albany, NY 12205

**Re: Limited Pre-Rehabilitation Asbestos Containing Materials Inspection Report
Mariaville Road Bridge over NYS Thruway I-87 Rehabilitation
Town of Rotterdam, Schenectady County, New York**

Dear Mr. Adamczak,

On February 11, 2026, Azar Design Co (Azar) performed a Limited Pre-Rehabilitation Inspection (Inspection) for asbestos containing materials (ACMs) at the above reference location (Site). The Inspection was performed in conjunction with proposed Element Specific Repair activities as presented within the project scope.

ACM Inspection Methodology

The Inspection, conducted by Mr. Eric Dixon of Azar utilized limited destructive methods to collect representative samples of homogeneous suspect ACMs at the Site, subject to potential disturbance during project execution. Mr. Dixon is a United States Environmental Protection Agency (USEPA) accredited Asbestos Hazardous Emergency Response Act (AHERA), and New York State Department of Labor (NYSDOL) certified asbestos building inspector (NYSDOL certification #26-6IICP-SHAB). The Inspection was conducted in accordance with USEPA National Emissions Standards for Hazardous Air Pollutants (NESHAPS), the Occupational Safety and Health Administration's (OSHA) regulation 29 CFR 1926.1101, and NYSDOL Part 56, Title 12 of the Official Compilation of Codes, Rules, and Regulations of the State of New York (Code Rule 56).

The following summarizes the sampling protocol applied:

- A minimum of two (02) samples were collected from each readily visible and accessible suspect homogeneous non-surfacing material in accordance with Code Rule 56.

Buffalo
295 Main Street
Suite 200
Buffalo, NY 14203
716.856.3933

Albany
435 New Karner Road
Albany, NY 12205
518.452.1037

Ithaca
123 W. State Street
Suite 201
Ithaca, NY 14850
607.288.2088

Manhattan
215 West 94th Street
Suite 517
New York, NY 10025
212.372.4813

Queens
89-31 161st Street
Suite 901
Jamaica, NY 11432
718.374.3422

Philadelphia
123 S. Broad Street
15th Floor
Philadelphia, PA 19109
267.703.6655

- Homogeneous materials were quantified, assessed for condition, and collected following AHERA procedures. Each sample was assigned a unique identification number, logged, and relinquished under proper chain-of-custody protocol to Paradigm Environmental Services, Inc. (Paradigm) for laboratory analysis. Paradigm is certified by the National Institute of Standards and Technology (NIST) and are participants under the National Voluntary Laboratory Accreditation Program (NVLAP), and New York Environmental Laboratory Approval Program (ELAP).
- Samples were analyzed using polarized light microscopy (PLM) in accordance with New York State Department of Health (NYSDOH) ELAP Method 198.6. Per Code Rule 56, all non-organically bound non-friable samples analyzed by PLM reported as “Inconclusive-Trace” or “Inconclusive-No Asbestos Detected” were further analyzed by transmission electron microscopy (TEM) in accordance with NYSDOH ELAP Method 198.4. As per instructions from Azar, the laboratory completed the analysis using “positive stop” methodology. The “positive stop” analysis method processes the first sample and if determined through laboratory analysis to be ACM, the second duplicate sample(s) of the homogeneous sample grouping will not be advanced for further analysis.

ACM Inspection Results and Conclusions

Azar collected a total of twenty-one (21) samples from seven (07) homogeneous materials at the Site. Sampled materials included green paint (non-friable), green/grey/white paint (non-friable), grey/white protective sealant paint (non-friable), black asphalt/tar-like patching/repair material (non-friable), black bearing pads (non-friable), black tar patching/repair material (non-friable) and black expansion joint (non-friable).

The USEPA and OSHA define material as asbestos containing if an asbestos content of one percent (>1%) or greater is detected in a representative sample. *As a result of laboratory analysis, it was determined that asbestos concentrations in excess of one percent (>1%) or greater were not identified in any of the samples processed.*

A summary of the building materials sampled and determined to not contain asbestos is provided in Table 1 of the Attachments.

Should the scope of work change, or if additional materials which have not yet been sampled are encountered during demolition or rehabilitation activities, materials should be assumed to be asbestos containing until laboratory analysis proves otherwise.



AZAR
DESIGN
CO

FORMERLY FOIT-ALBERT ASSOCIATES

www.azardzn.com | Hispanic MBE / DBE


Please contact our office at (716) 856 -3933 ext. 203 with any questions or comments.

Sincerely,

AZAR DESIGN CO

Architecture, Landscape Architecture, Engineering and Surveying, P.C.

(Formerly Foit-Albert Associates, Architecture, Engineering and Surveying, P.C.)



Eric Dixon
Environmental Scientist

Attachments:

- Photolog
- Table 1 – Summary of Building Materials Not Containing Asbestos
- Sample Location Maps
- Analytical Reports/Chain-of Custody Documentation
- Asbestos Certifications



FORMERLY FOIT-ALBERT ASSOCIATES

www.azardzn.com | Hispanic MBE / DBE


PHOTOGRAPHIC DOCUMENTATION



Photograph 1 – View of bridge inner girders non-ACM green paint (ACM-1, ACM-2 & ACM-3).



Photograph 2 – View of bridge outer girders non-ACM green/grey/white paint (ACM-4, ACM-5 & ACM-6).



Photograph 3 – View of bridge superstructure non-ACM black bearing pads (ACM-7, ACM-8 & ACM-9).



Photograph 4 – View of abutment walls non-ACM white/grey concrete protective sealant paint (ACM-12, ACM-13 & ACM-14).



Photograph 5 – View of road surface non-ACM black asphalt/tar crack filler material (ACM-19, ACM-20 & ACM-21).



Photograph 6 – View of road surface non-ACM black asphalt patching/repair material (ACM-22, ACM-23 & ACM-24).



Photograph 7 – View of road surface non-ACM black expansion joint (ACM-25, ACM-26 & ACM-27).

TABLES

Table 1
Summary of Building Materials Not Containing Asbestos
Mariaville Road Bridge over Thruway I-87
Town of Rotterdam, Schenectady County, New York

Sample ID	Percent (%) Asbestos
Bridge Inner Girders - Paint - Green	
ACM-1	None Detected
ACM-2	None Detected
ACM-3	None Detected
Bridge Outer Girders - Paint - Green/Grey/White	
ACM-4	None Detected
ACM-5	None Detected
ACM-6	None Detected
Superstructure - Bearing Pads - Black	
ACM-7	N/A
ACM-8	N/A
ACM-9	N/A
Abutments - Protective Sealant Paint - Grey/White	
ACM-12	None Detected
ACM-13	None Detected
ACM-14	None Detected
Road Surface - Asphalt/Tar Crack Filler/Repair Material - Black	
ACM-19	None Detected
ACM-20	None Detected
ACM-21	None Detected
Road Surface - Asphalt Patching/Repair Material - Black	
ACM-22	None Detected
ACM-23	None Detected
ACM-24	None Detected
Road Surface - Expansion Joint - Black	
ACM-25	None Detected
ACM-26	N/A
ACM-27	N/A

SAMPLE LOCATION MAP

LEGEND

ACM - ## = SAMPLE COLLECTED -
NO ASBESTOS DETECTED

ACM - 19/20/21

ACM - 25/26/27


ACM - 4/5/6

ACM - 22/23/24

ACM - 1/2/3

ACM - 7/8/9

ACM - 12/13/14





AZAR
DESIGN
CO

Architecture, Landscape Architecture, Engineering and Surveying, P.C.
CERTIFICATE OF AUTHORIZATION NO. 01848

ACM SAMPLE LOCATIONS

MARIAVILLE ROAD BRIDGE OVER US I-90

HAZARDOUS MATERIALS SAMPLE LOCATION MAP

NEAR 890 MARIAVILLE ROAD
TOWN OF ROTTERDAM, NY 12036

REAL

REGISTRATION EXP. DATE

PROJECT STATUS

REVISION NUMBER	REVISION DATE

SCALE: AS NOTED

DATE	PROJECT MANAGER
03/05/2026	KIC

DRAWN BY:	CHECKED BY:
JJE	ED

PROJECT NO.: 220296.05

CUSTOMER: -

FA: -

SHEET: 1 OF 3

ENV - 01

LABORATORY ANALYTICAL REPORTS

PARADIGM

ENVIRONMENTAL SERVICES

1430-B Millersport Hwy., Williamsville, NY 14221 (Office) 716.775.5777

PLM & TEM BULK ASBESTOS ANALYSIS REPORT

via NYSDOH ELAP Method 198.1, 198.4 and 198.6

Client: Azar Design Co/Foit-Albert Associates

Job No: 0175-26B

Location: Mariaville Bridge Over Thruway I-87

Page: 1 of 6

220296.05

Sample Date: 2/11/2026

Sample Received Date: 2/23/2026

Client ID	Lab ID	Sampling Location	Description	PLM Asbestos Fibers Type & Percentage	PLM Total Asbestos	NOB	TEM Asbestos Fibers Type & Percentage	TEM Total Asbestos	PLM Non-Asbestos Fibers Type & Percentage	Non- Fibrous Matrix Material %
ACM-1	1525	Bridge Inner Girders	Green Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-2	1526	Bridge Inner Girders	Green Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-3	1527	Bridge Inner Girders	Green Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-4	1528	Bridge Outer Girders	Green/Grey/White Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-5	1529	Bridge Outer Girders	Green/Grey/White Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-6	1530	Bridge Outer Girders	Green/Grey/White Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-7	1531	Bridge Superstructure	Black Bearing Pad	<1.0% Residue Remaining. PLM and TEM Not Required.	N/A	✗	N/A	N/A	N/A	N/A
ACM-8	1532	Bridge Superstructure	Black Bearing Pad	<1.0% Residue Remaining. PLM and TEM Not Required.	N/A	✗	N/A	N/A	N/A	N/A
ACM-9	1533	Bridge Superstructure	Black Bearing Pad	<1.0% Residue Remaining. PLM and TEM Not Required.	N/A	✗	N/A	N/A	N/A	N/A
ACM-12	1534	Abutment Walls	White/Grey Concrete Protective Sealant Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%

KEY TO NOB COLUMN SYMBOLS

No Symbol in the NOB column denotes sample analyzed by ELAP Method 198.1 (PLM).

✓ NOB (non-friable organically bound) denotes material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.

✓ denotes material analyzed by ELAP Method 198.6 (PLM) per NYSDOH. This Method does not remove vermiculite and may underestimate the level of asbestos present in a sample containing greater than 10% vermiculite.

denotes material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.

X denotes sample prepped only by ELAP Method 198.6.

** Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

N/A - Not Applicable

Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

PLM Bulk Asbestos Analysis by New York State Department of Health, ELAP Method 198.1, 198.4 and 198.6 ("Polarized Light Microscopy and Transmission Electron Identifying and Quantitating Asbestos in Bulk Samples and in Non-Friable Organically Bound Bulk Samples.") or EPA 600/M4-82-020 per 40 CFR 763.

ELAP ID No.: 11955

PLM Date Analyzed: 2/25/2026

TEM Date Analyzed: 2/25/2026

PLM Analyst: G. Freeman

TEM Analyst: A. Maciejewski

Microscope: Olympus BH-2 #241709

Microscope: Hitachi 600 AB

Laboratory Results Approved By:
Asbestos Technical Director or Designee


Andrew Maciejewski

Paradigm Environmental Services, Inc. is not responsible for the data supplied by an independent inspector. New York State Department of Health Environmental Laboratory Program (ELAP) requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This report relates ONLY to the items received by the lab. This report must not be used to claim product endorsement by NYS ELAP or any agency of the U.S. Government. Quality control data (including 95% limits and laboratory or analysts' accuracy and precision) is available upon request.

0175-26B 2/26/2026

PARADIGM

ENVIRONMENTAL SERVICES

1430-B Millersport Hwy., Williamsville, NY 14221 (Office) 716.775.5777

PLM & TEM BULK ASBESTOS ANALYSIS REPORT

via NYSDOH ELAP Method 198.1, 198.4 and 198.6

Client: Azar Design Co/Foit-Albert Associates

Job No: 0175-26B

Location: Mariaville Bridge Over Thruway I-87

Page: 2 of 6

220296.05

Sample Date: 2/11/2026

Sample Received Date: 2/23/2026

Client ID	Lab ID	Sampling Location	Description	PLM Asbestos Fibers Type & Percentage	PLM Total Asbestos	NOB	TEM Asbestos Fibers Type & Percentage	TEM Total Asbestos	PLM Non-Asbestos Fibers Type & Percentage	Non- Fibrous Matrix Material %
ACM-13	1535	Abutment Walls	White/Grey Concrete Protective Sealant Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-14	1536	Abutment Walls	White/Grey Concrete Protective Sealant Paint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-19	1537	Road Surface	Black Asphalt/Tar Crack Filler Material	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-20	1538	Road Surface	Black Asphalt/Tar Crack Filler Material	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-21	1539	Road Surface	Black Asphalt/Tar Crack Filler Material	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-22	1540	Road Surface	Black Asphalt Patching/Repair Material	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-23	1541	Road Surface	Black Asphalt Patching/Repair Material	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-24	1542	Road Surface	Black Asphalt Patching/Repair Material	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-25	1543	Road Surface	Black Expansion Joint	Inconclusive No Asbestos Detected	0%	✓	None Detected	ND	None Detected	100%
ACM-26	1544	Road Surface	Black Expansion Joint	<1.0% Residue Remaining. PLM and TEM Not Required.	N/A	X	N/A	N/A	N/A	N/A

KEY TO NOB COLUMN SYMBOLS

No Symbol in the NOB column denotes sample analyzed by ELAP Method 198.1 (PLM).

✓ NOB (non-friable organically bound) denotes material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.

✓ denotes material analyzed by ELAP Method 198.6 (PLM) per NYSDOH. This Method does not remove vermiculite and may underestimate the level of asbestos present in a sample containing greater than 10% vermiculite.

denotes material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.

X denotes sample prepped only by ELAP Method 198.6.

** Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.

N/A - Not Applicable

Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

PLM Bulk Asbestos Analysis by New York State Department of Health, ELAP Method 198.1, 198.4 and 198.6 ("Polarized Light Microscopy and Transmission Electron Identifying and Quantitating Asbestos in Bulk Samples and in Non-Friable Organically Bound Bulk Samples.") or EPA 600/M4-82-020 per 40 CFR 763.

ELAP ID No.: 11955

PLM Date Analyzed: 2/25/2026

TEM Date Analyzed: 2/25/2026

PLM Analyst: G. Freeman

TEM Analyst: A. Maciejewski

Microscope: Olympus BH-2 #241709

Microscope: Hitachi 600 AB

Laboratory Results Approved By:
Asbestos Technical Director or Designee


Andrew Maciejewski

Paradigm Environmental Services, Inc. is not responsible for the data supplied by an independent inspector. New York State Department of Health Environmental Laboratory Program (ELAP) requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This report relates ONLY to the items received by the lab. This report must not be used to claim product endorsement by NYS ELAP or any agency of the U.S. Government. Quality control data (including 95% limits and laboratory or analysts' accuracy and precision) is available upon request.

0175-26B 2/26/2026

1430-B Millersport Hwy., Williamsville, NY 14221 (Office) 716.775.5777

PLM & TEM BULK ASBESTOS ANALYSIS REPORT
via NYSDOH ELAP Method 198.1, 198.4 and 198.6

Client: Azar Design Co/Foit-Albert Associates

Job No: 0175-26B

Location: Mariaville Bridge Over Thruway I-87

Page: 3 of 6

220296.05

Sample Date: 2/11/2026

Sample Received Date: 2/23/2026

[illegible]

KEY TO NOB COLUMN SYMBOLS

No Symbol in the NOB column denotes sample analyzed by ELAP Method 198.1 (PLM).

^v NOB (non-friable organically bound) denotes material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.

✓ denotes material analyzed by ELAP Method 198.6 (PLM) per NYSDOH. This Method does not remove vermiculite and may underestimate the level of asbestos present in a sample containing greater than 10% vermiculite.

denotes material analyzed by ELAP Method 198.6 (PLM) and 198.4 (TEM) as noted.

X denotes sample prepped only by ELAP Method 198.6.

**** Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials.**

N/A - Not Applicable

Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

PLM Bulk Asbestos Analysis by New York State Department of Health, ELAP Method 198.1, 198.4 and 198.6 ("Polarized Light Microscopy and Transmission Electron Identifying and Quantitating Asbestos in Bulk Samples and in Non-Friable Organically Bound Bulk Samples.") or EPA 600/M4-82-020 per 40 CFR 763.

ELAP ID No.: 11955

PLM Date Analyzed: 2/25/2026

TEM Date Analyzed: 2/25/2026

PLM Analyst: G. Freeman

TEM Analyst: A. Maciejewski

Microscope: *Olympus BH-2 #241709*

Microscope: Hitachi 600 AB

Laboratory Results Approved By:
Asbestos Technical Director or Designee

Andrew Maciejewski

Paradigm Environmental Services, Inc. is not responsible for the data supplied by an independent inspector. New York State Department of Health Environmental Laboratory Program (ELAP) requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This report relates ONLY to the items received by the lab. This report must not be used to claim product endorsement by NYS ELAP or any agency of the U.S. Government. Quality control data (including 95% limits and laboratory or analysts' accuracy and precision) is available upon request.

0175-26B 2/26/2026



CHAIN OF CUSTODY FOR BULK ASBESTOS ANALYSIS

☐ 179 Lake Avenue, Rochester, New York 14608
☒ 1430 Millersport Hwy, Buffalo, NY 14221

Office: 585-647-2530
Office: 716-775-5777

Client: Azar Design Co/Foit-Albert Associates

Contact: Eric Dixon

Phone Number: (716) 622-6881

Email Address for Data: edixon@azarzn.com

Turn Around Time: 1 ☐ 2 ☐ 3 ☐ 5 ☒ Other ☐

Material Type/Quantity: Friable X NOB X TEM X

Project Location: 220296.05 Mariaville Bridge over Thruway I-87

Client Mailing Address: 295 Main St #200
Buffalo, New York
14203

Results To: Eric Dixon

Date Sampled: 2/11/2026

Project Location: 220296.05 Mariaville Bridge over Thruway I-87

Client ID **Lab ID** **Sampling Location** **Type of Material** **Color**

1 ACM-1 1525 Bridge Inner Girders - Paint - Green

2 ACM-2 26 Bridge Inner Girders - Paint - Green

3 ACM-3 27 Bridge Inner Girders - Paint - Green

4 ACM-4 28 Bridge Outer Girders - Paint - Green/Grey/White

5 ACM-5 29 Bridge Outer Girders - Paint - Green/Grey/White

6 ACM-6 30 Bridge Outer Girders - Paint - Green/Grey/White

7 ACM-7 31 Bridge Superstructure - Bearing Pad - Black

8 ACM-8 32 Bridge Superstructure - Bearing Pad - Black

9 ACM-9 33 Bridge Superstructure - Bearing Pad - Black

10 ACM-10 Road Surface - Road Striping Paint - White

Sampled By: Eric Dixon **Date:** 2/11/2026

Transported to Paradigm By: Eric Dixon **Date:** 2/13/2026

Received By: Brian **Date:** 2/23/2026

By signing this form, client agrees to Paradigm Terms and Conditions (reverse).

*PLEASE EMPLOY POSITIVE STOP

Job #: 0175-263

Page 1 **of** 3

Date Logged In: 2/24/26

Logged In By: AM

OFFICE USE ONLY

ALL samples will be analyzed by the appropriate New York State Department of Health methods (198.1, 198.4 and 198.6) unless EPA 600/M4/82/020 per 40 CFR 763 and/or EPA 600/R-93/116 methods are requested.

CHECK TO AUTOMATICALLY PERFORM TEM ON NOBS ☒ **or provide TEM contact name:**

TOTAL NUMBER OF SAMPLES ON ALL CHAINS OF CUSTODY: 27



CHAIN OF CUSTODY FOR BULK ASBESTOS ANALYSIS

☒ 179 Lake Avenue, Rochester, New York 14608
☒ 1430 Millersport Hwy, Buffalo, NY 14221

Office: 585-647-2530
Office: 716-775-5777

Client:

Azar Design Co/Foit-Albert Associates

Contact:

Phone Number:

(716) 622-6881

Email Address for Data:

edixon@azardzn.com

Results To:

Eric Dixon

Turn Around Time:

1 ☐ 2 ☐ 3 ☐ 5 ☒ Other ☐

Date Sampled:

2/11/2026

Material Type/Quantity:

Friable ☒ NOB ☒ TEM ☒

Project Location:

220296.05 Mariaville Bridge over Thruway I-87

OFFICE USE ONLY

Job #:

0175-26B

Page 2 of 3

Date Logged In:

2/24/26

Logged In By:

AM

Client Mailing Address:

295 Main St #200

Buffalo, New York

14203

Client ID	Lab ID	Sampling Location	Type of Material	Color
1	ACM-11		~~Road Surface - Road Striping Paint - White, ε D~~	
2	ACM-12	Abutment Walls - Concrete Protective Sealant Paint - White/Grey		
3	ACM-13	Abutment Walls - Concrete Protective Sealant Paint - White/Grey		
4	ACM-14	Abutment Walls - Concrete Protective Sealant Paint - White/Grey		
5	ACM-15	Road Surface - Road Striping Paint - White ε D		
6	ACM-16	Road Surface - Road Striping Paint - Yellow ε D		
7	ACM-17	Road Surface - Road Striping Paint - Yellow ε D		
8	ACM-18	Road Surface - Road Striping Paint - Yellow ε D		
9	ACM-19	Road Surface - Asphalt/Tar Crack Filler Material - Black		
#	ACM-20	Road Surface - Asphalt/Tar Crack Filler Material - Black		

Sampled By:

Eric Dixon

Date:

2/11/2026

Transported to Paradigm By:

Eric Dixon

Date:

2/13/2026

Received By:

Brian

Date:

2/23/26

All samples will be analyzed by the appropriate New York State Department of Health methods (198.1, 198.4 and 198.6) unless EPA 600/M4/82/020 per 40 CFR 763 and/or EPA 600/R-93/116 methods are requested.

CHECK TO AUTOMATICALLY PERFORM TEM ON NOBS

☒

or provide TEM contact name:

TOTAL NUMBER OF SAMPLES ON ALL CHAINS OF CUSTODY:

2

By signing this form, client agrees to Paradigm Terms and Conditions (reverse).

*PLEASE EMPLOY POSITIVE STOP

10:35



CHAIN OF CUSTODY FOR BULK ASBESTOS ANALYSIS

☐ 179 Lake Avenue, Rochester, New York 14608
☒ 1430 Millersport Hwy, Buffalo, NY 14221

Office: 585-647-2530
Office: 716-775-5777

Client: Azar Design Co/Foit-Albert Associates

Contact: Eric Dixon

Phone Number: (716) 622-6881

Email Address for Data: edixon@azaradzn.com

Results To

Eric Dixon

Turn Around Time:

1 ☐ 2 ☐ 3 ☐ 5 ☒ Other ☐

Date Sampled

2/11/2026

Material Type/Quantity:

Friable ☒ X NOB ☒ X TEM ☒ X

Project Location:

220296.05 Mariaville Bridge over Thruway I-87

OFFICE USE ONLY

Job #:

0175-263

Page 3 of 3

Date Logged In: 2/24/26

Logged In By: AM

Client Mailing Address:

295 Main St #200

Buffalo, New York

14203

Client ID	Lab ID	Sampling Location	Type of Material	Color
1	ACM-21	1539	Road Surface - Asphalt/Tar Crack Filler Material - Black	
2	ACM-22	40	Road Surface - Asphalt Patching/Repair Material - Black	
3	ACM-23	41	Road Surface - Asphalt Patching/Repair Material - Black	
4	ACM-24	42	Road Surface - Asphalt Patching/Repair Material - Black	
5	ACM-25	43	Road Surface - Expansion Joint - Black	
6	ACM-26	44	Road Surface - Expansion Joint - Black	
7	ACM-27	45	Road Surface - Expansion Joint - Black	
8				
9				
#				

Sampled By:

Eric Dixon

Date:

2/11/2026

Transported to Paradigm By:

Eric Dixon

Date:

2/13/2026

Received By:

Eric Dixon

Date:

2/23/26

All samples will be analyzed by the appropriate New York State Department of Health methods (198.1,198.4 and 198.6) unless EPA 600/M4/82/020 per 40 CFR 763 and/or EPA 600/R-93/116 methods are requested.

CHECK TO AUTOMATICALLY PERFORM TEM ON NOBS

X

or provide TEM contact name:

TOTAL NUMBER OF SAMPLES ON ALL CHAINS OF CUSTODY:

2

By signing this form, client agrees to Paradigm Terms and Conditions (reverse).

*PLEASE EMPLOY POSITIVE STOP

16:35

ASBESTOS CERTIFICATION

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE



ERIC DIXON
CLASS(EXPIRES)
C ATEC (01/26) D INSP (01/26)
H PM (01/26)

CERT# 25-611CP-SHAB
DMV# 187836255

MUST BE CARRIED ON ASBESTOS PROJECTS

REPRODUCTION OF THIS CERTIFICATE IS A VIOLATION OF THE LAW



IF FOUND, RETURN TO:

NYSOL - L&C UNIT
ROOM 161A BUILDING 12
STATE OFFICE CAMPUS
ALBANY NY 12226



01213 007536127 93



Department
of Labor

WORKING FOR YOU

DIVISION OF SAFETY & HEALTH LICENSE AND CERTIFICATE UNIT, STATE OFFICE CAMPUS, BLDG. 12, ALBANY, NY 12226

ASBESTOS HANDLING LICENSE

Azar Design Co, Architecture, Landscape Architecture, Engineering and Surveying, P.C.
295 Main Street, Suite 200, Buffalo, NY 14213

License Number: 37054

License Class: RESTRICTED

Date of Issue: 01/16/2026

Expiration Date: 01/31/2027

Duly Authorized Representative: Kurt Knoell

This license has been issued in accordance with applicable provisions of Article 30 of the Labor Law of New York State and of the New York State Codes, Rules and Regulations (12 NYCRR Part 56). It is subject to suspension or revocation for a (1) serious violation of state, federal or local laws with regard to the conduct of an asbestos project, or (2) demonstrated lack of responsibility in the conduct of any job involving asbestos or asbestos material.

This license is valid only for the contractor named above and this license or a photocopy must be prominently displayed at the asbestos project worksite. This license verifies that all persons employed by the licensee on an asbestos project in New York State have been issued an Asbestos Certificate, appropriate for the type of work they perform, by the New York State Department of Labor.

Vicki Mockler, Director
For the Commissioner of Labor

EXCELSIOR

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER



Expires 12:01 AM April 01, 2026
Issued April 01, 2025

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MR. ANDREW MACIEJEWSKI
PARADIGM ENVIRONMENTAL SERVICES
1430-B MILLERSPORT HIGHWAY
WILLIAMSVILLE, NY 14221

NY Lab Id No: 11955

is hereby APPROVED as an Environmental Laboratory for the category
ENVIRONMENTAL ANALYSES SOLID AND HAZARDOUS WASTE
All approved subcategories and/or analytes are listed below:

Miscellaneous

Asbestos in Friable Material	Item 198.1 of Manual
	EPA 600/M4/82/020
Asbestos in Non-Friable Material-PLM	Item 198.6 of Manual (NOB by PLM)
Asbestos in Non-Friable Material-TEM	Item 198.4 of Manual

Serial No.: 70696

Property of the New York State Department of Health. Certificates are valid only at the address shown and must be conspicuously posted by the laboratory. Continued accreditation depends on the laboratory's successful ongoing participation in the Program. Consumers may verify a laboratory's accreditation status online at <https://apps.health.ny.gov/pubdoh/applinks/wc/elappublicweb/>, by phone (518) 485-5570 or by email to elap@health.ny.gov.

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER



Expires 12:01 AM April 01, 2026
Issued April 01, 2025

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MR. ANDREW MACIEJEWSKI
PARADIGM ENVIRONMENTAL SERVICES
1430-B MILLERSPORT HIGHWAY
WILLIAMSVILLE, NY 14221

NY Lab Id No: 11955

*is hereby APPROVED as an Environmental Laboratory for the category
ENVIRONMENTAL ANALYSES AIR AND EMISSIONS
All approved subcategories and/or analytes are listed below:*

Miscellaneous

Asbestos

40 CFR 763 APX A No. III
YAMATE, AGARWAL GIBB
NIOSH 7402

Fibers

NIOSH 7400 A RULES

Serial No.: 70697

Property of the New York State Department of Health. Certificates are valid only at the address shown and must be conspicuously posted by the laboratory. Continued accreditation depends on the laboratory's successful ongoing participation in the Program. Consumers may verify a laboratory's accreditation status online at <https://apps.health.ny.gov/pubdoh/applinks/wc/elappublicweb/>, by phone (518) 485-5570 or by email to elap@health.ny.gov.