

TAS 26-10A / D215078
Replace Waterline at the Port Byron Service Area, MP 310.2 EB
in Cayuga County

QUESTIONS AND ANSWERS

December 16, 2025 (Revised on December 31, 2025)

- Q1. Will there be a pre-bid meeting for this project?
- A1. There will not be a pre-bid meeting for this project.
- Q2. The report prepared by Colliers classifies the pipe as HDPE, but the plans indicate DIP. Which is preferred?
- A2. ~~While the plans indicate DIP, HDPE is considered a reasonable alternative here.~~ Refer to Amendment #1.
- Q3. I am unable to send an email to Nick Tario, the registered Architect at the Thruway Authority for this project. How can I reach him?
- A3. Mr. Tario's correct email address is: Nicholas.Tario@thruway.ny.gov.

December 31, 2025

- Q4. Under Earthwork Item 627.0031 25 Specification Summary 1.02 A, it states: Site work needed for the construction of the building's addition, including earthwork and preparation. I do not see a building addition on the project plans. Is this specification part of the contract? If so, where are the plans?
- A4. On Proposal Page 21, under Earthwork Item 627.0031 25 Specification Summary 1.02 A., Delete the sentence that currently reads: "Site work needed for the construction of the building's addition, including earthwork and preparation." and Replace with: "Site work needed for the construction of the Master Meter Vault including earthwork and preparation.". Also, refer to Amendment #1.
- Q5. For the asphalt pavement area on Drawing Number PP-04, is the restoration for that asphalt area trench work? Or do you want us to square it and make it one larger patched area.
- A5. The asphalt pavement area on Drawing Number PP-04, the restoration for that asphalt area shall be trench work.